

ДОРАБОТКА : HYDRAULIC SUSPENSION UNION

Привлекаемые автомобили : XANTIA с гидравтической подвеской (with or without SC.CAR).

Применение, начиная с номера OPR: 8057.

The CITROEN hydraulic union replaces the ISO union.

ПРИМЕЧАНИЕ : SC.CAR : Система Citroën активного управления поперечными колебаниями.

1. Описание

The new CITROEN union is fitted to the end of 10 mm diameter pipes, connecting the following components :

- Front suspension regulator - Suspension strut supports (спереди)
- Rear suspension regulator - cylindres de suspension (задняя)

This modification entails the evolution of the following components :

- Suspension regulators (передний и задний)
- Suspension strut supports (спереди)
- cylindres de suspension (задняя)




Рисунок : B4DP001D

A - Старая конструкция : штуцер ISO.

B - Новая конструкция : штуцер CITROEN.

(1) Соединительный конус (dimension across the flats) :

- Старая конструкция : 17 мм
- Новая конструкция : 16 мм

(2) End of the pipe.

(3) Герметизирующую панель (steel bush with bonded seal).

(4) Body of the part.

ВНИМАНИЕ : The thread on the old and new unions is the same : M16 x 150. Смешивание старых и новых деталей запрещено.

1.1. Suspension regulators (передний и задний)




Рисунок : V3BP13HD

" a " Housing of the CITROEN union.

Новая конструкция : The hexagonal section of the union has a machined part at "b".

1.2. Suspension strut supports (спереди)




Рисунок : V3BP13JC

" c " Housing of the CITROEN union.

Идентификация оснащения :

- Старая конструкция : The side "d" is not machined, and is protected by a coat of black paint
- Новая конструкция : The side "d" is machined

1.3. cylindres de suspension (задняя)




Рисунок : ВЗВР13КД

" e " Housing of the CITROEN union.

Идентификация оснащения :

- Старая конструкция : The diameter "f" is not machined
- Новая конструкция : The diameter "f" is machined

ПРИМЕЧАНИЕ : To identify the suspension cylinder on the vehicle, it may have to be released and moved backwards.

2. Работы

ОБЯЗАТЕЛЬНО : In the event of a problem, please inform the CITROEN After Sales technical assistance team by "Techfile Info".

2.1. Взаимозаменяемость

Служба запасных частей продает и старые и новые детали.

ВНИМАНИЕ : Смешивание старых и новых деталей запрещено.

ПРИМЕЧАНИЕ : The thread on the old and new unions is the same . Check that the parts match before assembly.

ОБЯЗАТЕЛЬНО : Check the union is sealed by varying the height of the vehicle, engine running.

2.2. Рекомендации - меры предосторожности

The LHM mineral hydraulic fluid is the only suitable fluid to be used.

2.3. Рекомендации - меры предосторожности : Меры предосторожности перед проведением любых работ

Очистите :

- The area in which work is to be done
- трубок
- The component to be removed

Отсоединить кабель от отрицательной клеммы аккумуляторной батареи.

Use either petrol or lead free petrol, but no other product.

2.4. Рекомендации - меры предосторожности : Precautions to be taken during the dismantling operation

Blank off the metal pipes with plugs.

Заглушить отверстия в гидравлических органах пробками.

2.5. Рекомендации - меры предосторожности : Precautions to be taken during assembly

The steel pipes should be blown through with compressed air.

The hydraulic components should be cleaned either with ordinary petrol, or with lead-free petrol, and blown through with compressed air.

ОБЯЗАТЕЛЬНО : Каждый раз при проведении работ заменяйте гидравлические затворы.

The metal pipes are protected with an EPOXY paint.

ВНИМАНИЕ : Make sure, before effecting the assembly, that neither the pipe, nor its location, are carrying EPOXY paint particles.

2.6. Рекомендации - меры предосторожности : Fitting a new hydraulic union




Рисунок : E1AP03BC

Fit the seal (3) to the pipe (2).

The seal must be up against the shoulder of the pipe.




Рисунок : E1AP03CC

Centre the pipe into the bore, lining it up with the centre line of the hole and avoiding all stress.

ВНИМАНИЕ : Start screwing in the union-nut (1) by hand. If necessary, slacken the component fixing to make this operation easier.
Слегка затянуть гайку . Excessive tightening may cause a leak as a result of the deformation of the pipe.

Моменты затяжки		
труба	Диаметр	Момент затяжки
New union	10 мм	2,5 дН.м
Old union	10 мм	3 дН.м

Should a leak occur, check the tightening torque of the union-nut.

If the leak does not stop, check the condition of the tube and renew the sleeve seal if need be.

2.7. Verifications after repairs

Check the hydraulic pipe connections for leaks.

The hydraulic pipes should neither touch a fixed or movable component or exert a stress upon them.

Гарантия :

- 2 mm at least between a fixed tube and a fixed part
- 10 mm min. between a fixed tube and a movable part